

**CASCADE - WARM LAKE**  
**Terracon Project No. 62005055A**  
**PHOTO LOG**

The odometer reading 0.0 is located at the intersection of Cascade Warm Lake Road and Highway 55.  
This current project begins approximately at the summit and continues to Warm Lake.  
The summit is approximately odometer reading 15.5 miles±.

Odometer Reading		
Photo No.	(miles)	Notes
0001	2.8	Turnout - west end of project
0002	2.8	Section change near start of project
0003	5.2	FH-1; WB lane near cut, rutted
0004	6.8	FH-2; EB lane, surface ravelling
0005	6.8	FH-2; Surface ravelling
0006	6.8	FH-2; WB lane, surface ravelling
0007	9.2	"Bump"; 2 consecutive patches
0008	9.5	FH-4; WB lane
0009	9.5	FH-4; Loss of surface treatment
0010	9.5	FH-4; Looking WB
0011	10.1	In - filled wheelpaths (EB view)
0012	11.6	FH-5; WB lane (EB view)
0013	11.6	FH-5; EB view
0014	11.6	FH-5; Loss of surface treatment
0015	11.8	FH-6; EB view near FR 418
0016	12.9	WB view
0017	13.6	FH-9; WB lane near cut (EB view)
0018	13.6	FH-9; WB view, rutted WB lane
0019	14	FH-10; EB view
0020	14	FH-10; WB view
0021	14	FH-10; Drop inlet off WB lane
0022	14.2	FH-11; Cut area (EB view)
0023	14.2	FH-11; 2 cut sections
0024	14.2	FH-11; Loss of surface treatment, transverse crack
0025	14.2	FH-11; EB view
0026	14.2	FH-11; Loss of aggregate, cracking, snowplow grooves
0027	14.5	FH-12; EB view
0028	14.5	FH-12; Transverse crack, snowplow grooves
0029	15	FH-13; WB lane, snowplow grooves, patch at cut (EB)
0030	15	FH-13; EB lane patch at cut
0031 0032	15.3	Cut section, snowplow grooves, minor ravelling
0033	16.1	FH-14; Core 14, EB view
0024	16.1	Below summit; near FH-14
0025	16.1	FH-14; (WB view)
0036	17.1	Core 15; cut in granite
0037	17.9	FH-16; Rutting near west end (Fill area)
0038	17.9	FH-16; West end of cut
0039	17.9	FH-16; Ravelling, transverse and longitudinal cracks
0040	17.9	FH-16; WB view near east end of cut
0041	18.5	Steep cut in granite; up to 1-inch cracks in EB lane
0042	18.5	Cracks in outside wheelpath and rutting (EB)
0043	18.9	FH-18; Heave in WB lane
0044	19.5	Change in section near entrance to Clear Creek Road (EB view)
0045	20.3	FH-19; WB view
0046	20.3	FH-19; WB lane, cracking, ravelling, rutting
0047	26.2	Bleeding chip seal
0048	27.5	Bleeding chip seal near Firefighter Memorial Trail
0049	N/R	Warm Lake
0050	21.7	FH-20; patched, rutted, cracked, EB lane
0051	N/R	WB view of bleeding surface (west of beginning of project)

N/R not recorded

0001



0002



0003



0004







0006



0007





0008



B 0009

0010



0011



0012

575



0013





0014



0015



0016





0017

0018





0019





0020





0021

0022



0023



0024



0025





0026



0027



0028





0030



0031





0032



0033



0034



0035





0036





0037



0038

0039



0040





0041



0042



0043



0044



0045



0046





0047



0048



0049



0050



0051

